LINITOP

LINITOP ACRYL PRIM

Water-based impregnation woodstain





- Composition: Density (at +20°C): Flash point:
- Viscosity:
- Solid content:
- VOC:
- Packaging:Shelf life:
- Storage conditions: Appearance in the can:
- Appearance of the dry product:
- Colours:
- Cleaning of the tools: **Conditions of application:**

• Safety:

Coverage: Drying (data at +20°C and 50% relative humidity):

Alkyd and acrylic resins. 1.020 ± 0.05 . Not classified as inflammable. Semi-fluid liquid. $18\% \pm 2.$ EU limit value for this product (cat A/e): 130 g/l (2010). This product contains a maximum of 65 g/l VOC. 1 | - 5 | and 10 |. At least 2 years in the closed original packaging. Keep away from frost and high temperatures. Coloured gel.

Matt.



Brush, roller, spray gun.

Ready to use. Water.

Respect the conditions and instructions stipulated by the manufacturer. Do not apply at an ambient temperature of less than $+10^{\circ}$ C or greater than $+30^{\circ}$ C. Relative humidity: 50%.

- 13 to 16 m²/l.
- Dust-dry: 1 h.
- Recoatable: 4 h.

If covered with a solvent-based solution, wait at least 12 h. Refer to the safety data sheet and the text given on the packaging, in accordance with the applicable legislation.

• Tools: \circ **Dilution:**

LINITOP

Surface preparation	 Use on wood whose usage, nature, quality, treatments and preparation comply with the applicable standards and DTU (DTU 59.1). The inspection and preparation of the surface are the responsibility of the user. The wood must be dry, clean, in sound condition, free of millglaze and properly prepared (degrease, sand, dust off). On new wood: Sand (grit 120) to encourage and optimise the opening of the pores. On old wood: Make the surface bare by sanding or stripping.
Recommendations before application	 Ready for use. Shake well before application. Do not apply at an ambient air and wood temperature of less than +10°C and greater than +30°C. The relative humidity will be of the order of 50% for optimum drying. Complies with the applicable standards and DTU. Protect everything that does not have to be treated. The moisture of the wood must not be greater than 15%. To protect the wood against UV, do not use «colourless» or «white» by itself outside as the finish coat. Always finish with 2 coloured coats.
Directions for use	 According to the condition of the surface: New wood: After sanding, apply the protection according to one of the two systems proposed below. Greyed wood: Clean with Wood Cleaner**, rinse and allow to dry. Sand (grit 120) if necessary. Apply the protection. Oiled, darkened wood: Remove the oil with Wood Oil Cleaner**, neutralise with Wood Cleaner**, rinse and allow to dry. Sand (grit 120) if necessary. Apply the protection. Oiled, darkened wood: Remove the oil with Wood Oil Cleaner**, neutralise with Wood Cleaner**, rinse and allow to dry. Sand (grit 120) if necessary. Apply the protection. Wood to be stripped: consult us. 1 - Impregnation undercoat system: Apply a generous coat of Linitop Acryl Prim. After completely drying, on wood with stable dimensions and for a durable finish, end with 2 coats of Linitop Classic** or Linitop Solid**. The last two coats must be coloured* outside. 2 - Three coat protective system: Apply 3 coats of Linitop Acryl Prim. The last two coats must be coloured* for outdoor use. NB: Pay special attention to grooves and butts. When applying with a spray gun, smooth with a brush to avoid running and to aid penetration of the product.
Advice of the professionals	 Always apply Linitop Acryl Prim in the direction of the grain. On new wood or bare wood, that is not durable and has not been treated with a preservative, it is recommended first treating the wood with an insecticide, fungicide and anti-blue stain agent. Consult us. Coloured base before finishing: Apply a coat of Linitop Acryl Prim. After drying and without sanding, complete with two coats of Acryl Vernis** or Acryl Parket**, sand between the two coats.
Maintenance	 For the three coat protection system: Normal restoration: Apply one or two coats depending on the condition after brushing or sanding. Late restoration: On a highly damaged surface, make the wood bare by sanding or stripping, and then apply three coats. NB: After sanding/stripping, always carefully clean the surface.

For further help or advice please contact us on: Belgium: +32 (0)10 420090 - 0800 95549 France: +33 (0)1 60 86 48 70

or consult our site: www.linitop.com

This notice cancels and replaces all previous notices on the same product. The advice provided, in particular on the maintenance, is only indicative and cannot substitute for an appropriate description of the nature and condition of the surface to be worked on. With technical developments continually occurring, it is for our customers to check, before application, with our services that this notice has not been replaced by a more recent edition.



URIEU

Durieu S.A. 91070 BONDOUFLE - France T. +33 (0)1 60 86 48 70 F. +33 (0)1 60 86 84 84 info@durieu.com www.durieu.com

Durieu Coatings S.A. / N.V. New Tech Center Avenue Albert Einstein 2 A **1348 Louvain-La-Neuve Belgique / België** T. +32 (0)10 420 090 F. +32 (0)10 420 099 info@durieucoatings.com www.durieucoatings.com

🔗 0800 95 549

www.linitop.com

03/11

ed'fields